

APPENDIX A  
NOTICE OF VIOLATION

Tennessee Valley Authority

License Nos. CPPR-91  
CPPR-92

Based on the NRC inspection September 1 - October 17, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10CFR50.55(e), the holder of construction permit shall notify the Commission within 24 hours of each deficiency found in design and construction, which, were it to remain uncorrected, could have affected adversely the safety of operations of the nuclear power plant at any time throughout the expected lifetime of the plant, and which represents a significant breakdown in any portion of the quality assurance program in accordance with the requirements of Appendix B or a significant deficiency in construction of a component which will require extensive evaluation or repair to establish the adequacy of the system to perform its intended function.

Contrary to the above, as of October 17, 1980, the licensee had not notified the Commission of the following significant deficiencies.

1. Approximately one-third of 1312 spent fuel rack cells did not meet acceptance criteria for cell verticality, levelness, and drag resistance and will or has required extensive evaluation and repair to establish their adequacy.
2. Hundreds of safety-related valves installed in systems, including safety injection system, had nameplate and other supplied certifications which did not meet procurement specifications.

This is an infraction.

8108050593