



NRC FORM 391M PART 1 <small>(10-2003) 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Gifford Medical Center 44 South Main Street Randolph, Vermont 05160		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT No 2007001			
3. DOCKET NUMBER(S) 030-03295	4. LICENSE NUMBER(S) 44-13976-01	5. DATE(S) OF INSPECTION 5/21/2007	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input type="checkbox"/> 2. Previous violation(s) closed.			
<input type="checkbox"/> 3. The violation(s), as specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1800, to exercise discretion, were satisfied.			
<input type="checkbox"/> Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):			
<input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
<p>10 CFR 35.14(b) requires, in part, that a licensee shall notify the Commission no later than 30 days after a Radiation Safety Officer permanently discontinues performance of duties under the license.</p> <p>Contrary to the above, the licensee did not notify the NRC about the permanent discontinues performance of the RSO in December 2006, nor the change of a new RSO in April 2007.</p>			
Licensee's Statement of Corrective Actions for Item 4, above:			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
<small>Title</small>	<small>Printed Name</small>	<small>Signature</small>	<small>Date</small>
LICENSEE'S REPRESENTATIVE	Marjorie Judd		7/31/07
NRC INSPECTOR	Shirley Xu		7/15/2007

NRC FORM 391M PART 1 (Rev. by RI 07/06)

P:\inspection\NRC591MPart1\2007\44-13976-01.2007-001.591P1.vwp

SUNSI Review Completed By: /RA/

Public

Non-Sensitive