

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Cardinal Health
628 Hebron Avenue, Building 4
Glastonbury, Connecticut 06033

REPORT Nos 2007005

2. NRC/REGIONAL OFFICE

**U.S. Nuclear Regulatory Commission
Region I, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415**

3. DOCKET NUMBER(S)
030-36973

4. LICENSE NUMBER(S)
34-29200-01MD

5. DATE(S) OF INSPECTION
June 21, 2007 - August 15, 2007

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

The NCV involves the failure, in accordance with 10 CFR 32.72(a)(4), to ensure that the label on two vials, containing 4.0 and 5.5 millicuries of iodine-131 each, were correlated with the information on their respective transport radiation shield labels. Specifically, the pharmacy staff placed the first vial in the second vial's transport radiation shield and visa versa. The root cause of the NCV was the switching of the two transport shields with their respective labels by the individual who wrapped the package preparation for shipping. The corrective action included having the individual compounding the iodine-131 capsule apply the transport shield label and wrap the transport shield.

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|-----------------|-----------|---------|
| LICENSEE'S REPRESENTATIVE | WILLIE REGITS | | 9/19/07 |
| NRC INSPECTOR | Stephen Hammann | | 9/11/07 |

RECEIVED SEP 21 2007

SUNSI Review Completed By: / RA / STH

Public

Non-Sensitive

100% Recycled fiber
80% Post-Consumer

Extremely Urgent

This envelope is for use with the following services:

UPS Next Day Air®
UPS Worldwide Express™
UPS 2nd Day Air

Call 1-800-854-8769

For U
contri
Air se
listed

For U
docun
of pag

Do not
envelo
or mor

Do not

DONNA SNIDER
614-757-3124
CARDINAL HEALTH
7000 CARDINAL PLACE
DUBLIN OH 43017

LTR 1 OF 1

SHIP TO:
KEN LAMBERT
US NUC. REG. COMMISSION, REGION III
2443 WARRENVILLE ROAD
LISLE IL 60532-3673



IL 603 9-03



UPS 2ND DAY AIR

TRACKING #: 1Z 05R 4W8 02 9892 4356

2



BILLING: P/P

Cost Center: 4210



CE 9.5 16.0 W072860 69-04 07/2007

US NUC REG COMMISSION REGION III
2443 WARRENVILLE RD

LISLE IL 60532-3673

P: **YELLOW** s: **4BB**

I: **405**

0402-8430

1Z05R4W80298924356

UNITED STATES POSTAL SERVICE
75 8014 NIP 8.2.1 0114420

ipe for:

documents
from the top.

WiFi

Use this
or linkjet

<https://www.campusship.ups.com/cship/create?ActionOriginPair=print> PrinterPage&POPUP_LEVEL... 9/19/2007

International Shipping Notice - Carriage hereunder may be subject to the rules relating to liability and other terms and/or conditions established by the Convention for the Unification of Certain Rules Relating to International Carriage by Air (the "Warsaw Convention") and/or the Convention on the Contract for the International Carriage of Goods by Road (the "CMR Convention"). These commodities, technology or software were exported from the U.S. in accordance with the Export Administration Regulations. Diversion contrary to U.S. law prohibited.

010195103 05/05 PAC United Parcel Service, Louisville, KY