

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

830 Power Building

JUN 12 1978

Central file
50-570
371

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 1217
230 Peachtree Street, NW.
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 78-05 - RII:JPO
50-259, -260, -296, -327, -328, -390, -391, -438, -439, -518,
-519, -520, -521, -553, -554, -566, -567 - SEQUOYAH, WATTS BAR,
BELLEFONTE, HARTSVILLE, PHIPPS BEND, AND YELLOW CREEK NUCLEAR
PLANTS

In response to your April 14, 1978, letter which transmitted IE
Bulletin 78-05, we are submitting the following results of our
investigations for Sequoyah, Watts Bar, Bellefonte, Hartsville,
Phipps Bend, and Yellow Creek Nuclear Plants.

A review of the affected nuclear plants revealed that TVA neither uses,
nor do we plan to use, circuit breaker auxiliary contact mechanisms
of the type described by IE Bulletin 78-05 in Class IE circuits of
the subject plants.

Very truly yours,

J. E. Gilleland

J. E. Gilleland
Assistant Manager of Power

cc: Office of Inspection and Enforcement
Division of Reactor Operations Inspection
U.S. Nuclear Regulatory Commission
Washington, DC 20555

A/O 2

GD