

TELEPHONE REPORT

FACILITY: Watts Bar 1 & 2
Bellefonte 1 & 2

DOCKET #: 50-390 & 50-391
50-438 & 50-439

DATE: December 2, 1977 TIME: 4:15 p.m. LIC. OCC. #: _____

SUBJECT: SCORE ON MAIN STEAM ISOLATION VALVES

DESCRIPTION OF OCCURRENCE: Atwood and Morrill (valve vendor) was reworking some
valves and found a deep score (0.020 inches deep by 1/8-inch wide) on a
valve body cylinder bore. The scoring had occurred during the seal blow-
down test which was performed without lubrication according to TVA
specifications. Four valves which had been shipped to Watts Bar and four
to Bellefonte had been subjected to the same test. These valves have
been returned to the vendor for examination.

L. E. Foster
December 5, 1977

AD 4
GD