

 Lost Creek SRL, LLC
 Limon, Colorado, USA


 LATA INTERNATIONAL, INC.
 Fort Collins, Colorado, USA

Legend
 MU Proposed Mine Unit
 • Drill Hole
 - Fault
 Thickness < 10 feet
 Thickness 10-20 feet
 Thickness 20-30 feet
 Thickness > 30 feet

PLATE 2.6-2a
Isopach Map of the Lost Creek Shale
Lost Creek Permit Area
 Issued For: NRC TR1.0 Drawn By: HA
 Issued/Revised: 10.10.07
 Drawing No.: NRC TR1.0 PLATE2.6-2a 10.10.07

D-10