

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Allen Park Cardiology, P.C. REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 03034417		4. LICENSE NUMBER(S) 21-26792-01	5. DATE(S) OF INSPECTION October 31, 2007
6. INSPECTION PROCEDURES USED 87130 (10/24/02)		7. INSPECTION FOCUS AREAS 03.01 - 03.07	
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Linda Ferkalo or Denise Gorans	4. TELEPHONE NUMBER 313-928-2333
<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: October 2012		
<input type="checkbox"/> Field Office _____			
<input type="checkbox"/> Temporary Job Site _____			

PROGRAM SCOPE

The licensee was a medical clinic authorized by the license to use any byproduct material identified in 10 CFR 35.200 for any imaging and localization procedure approved in 10 CFR 35.200 (limited to cardiovascular clinical procedures excluding xenon-133 and aerosols) at the location specified on the license. The nuclear medicine department was staffed with two nuclear medicine technologists (NMTs) who routinely conducted an average of 40 patient procedures per week. The licensee received Cardiolite® unit doses as ordered from a local nuclear pharmacy. All waste was held for decay-in-storage (DIS) or returned to the nuclear pharmacy as a limited quantity shipment. No change in NMTs or RSO since the previous inspection.

Performance Observations

During the inspection, the licensee's NMT demonstrated/discussed: (1) package check-in procedures and wipe test counting; (2) dosimetry; (3) dose calibrator tests; (4) unit dose handling procedures; (5) security of licensed material; (6) radiation safety program audits; (7) rad waste procedures; and (8) closure of one SL IV violation pertaining to weekly wipe tests.