



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532-4352

December 4, 2007

John A. Newland, President
JANX Integrity Group
P. O. Box 190
8500 E. Michigan Avenue
Parma, MI 49269

SUBJECT: NRC INSPECTION REPORT 030-1772/07-04 (FORM 591M Part 1)

Dear Mr. Newland:

This letter refers to the routine inspection conducted on November 6, 2007 at a temporary job site in Rock Springs, Wyoming. The inspection results were discussed with you during a final telephonic exit briefing conducted on November 30, 2007.

This inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements, and observation of activities in progress. Within the scope of this inspection no violations of NRC requirements were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,



John R. Madera, Chief
Materials Inspection Branch

Docket No.: 030-11772
License No.: 21-16560-01

Enclosure:
NRC Form 591M

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Jan X, Inc 8500 E. Michigan Ave Parma, Michigan 49269 REPORT NUMBER(S) 2007-004		2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive Arlington, Texas 76011-4005	
3 DOCKET NUMBER(S) 030-11772	4. LICENSEE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION November 6, 2007	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Lawrence Donovan	<i>Ken Lambert for</i>	11/30/07
NRC INSPECTOR	Lawrence Donovan	<i>Ken Lambert for</i>	11/30/07

Docket File Information
**SAFETY INSPECTION REPORT
 AND COMPLIANCE INSPECTION**



1. LICENSEE Jan X Inc REPORT NUMBER(S) 2007-004		2. NRC/REGIONAL OFFICE USNRC Region IV	
3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION November 6, 2007	
6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3320	2. PRIORITY 1	3. LICENSEE CONTACT Rusty Cole and Darrell Jackson	4. TELEPHONE NUMBER 517-531-8210
Main Office Inspection _____ Field Office _____		Next Inspection Date: _____	
<input checked="" type="checkbox"/> Temporary Job Site El Paso Field Services, Rock Springs WY			

PROGRAM SCOPE

This was a temporary job site inspection of a NRC licensee who was performing industrial radiography in the Rock Springs Wyoming vicinity. Jan X is a large Region III industrial radiography licensee with its corporate office in Parma Michigan. Jan X has 15 divisions throughout the United States in West Virginia, Tennessee, Pennsylvania, Oklahoma, North Carolina, Ohio, Michigan, Louisiana, Kentucky, Indiana, Georgia and New Jersey. Jan X had one crew at the Rock Springs Wyoming job location. The radiographer showed his current radiographer's card upon request by the inspector. The licensee was able to provide the inspector with all required documents as required by 10 CFR 34.89. These documents included a copy of the NRC licensee, 10 CFR parts 19, 20 and 34, utilization records, shipping papers, operating and emergency procedures and evidence of radiation survey meter (2), alarming rate meters (2), and personal ionization chamber (PIC-2) calibration records. Daily radiation survey reports were reviewed which contained daily PIC start and finish dose readings, confirmation of instrumentation current calibration and due dates. Both the radiographer and radiographer's assistant satisfactorily demonstrated the operations check of their alarming rate meters. The source calibration record showed current leak test within the previous 6 months. No violations or deviations to NRC regulations were noted.