

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 7, 1980

APR 9 AIO: 09

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


WATTS BAR NUCLEAR PLANT UNIT 1 - INCORRECT BORE IN DRAVO TRANSMITTER  
BOSS - NCR 1942R - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. Thomas on January 7, 1980, in accordance with 10 CFR 50.55(e). An interim report was submitted on February 5, 1980. Enclosed is our second interim report. We expect to submit our next report by June 6, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8019  
SE  
1/1