

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2
INSUFFICIENT ANALYSIS OF THREE INCH FIRE
PROTECTION LINES
NCR WBN CEB 8005
10 CFR 50.55(e)
First Interim Report

Description of Condition

TVA has discovered that a 3-inch fire protection line, located in the auxiliary building was not properly analyzed. The layout drawings did not provide sufficient dimensions, and the line was thought to be two inches in diameter when, in fact, it was three inches in diameter and thus should have been rigorously analyzed.

Corrective Action

The 3-inch fire protection line will be rigorously analyzed and supports will be added as necessary.

8007140 427