

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

JAN 1 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement,
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT INSTALLATION OF SEISMIC
PIPE HANGER ANCHORS - NCR CAQR M-31 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Bruce Cochran on December 20, 1978. Enclosed is our first interim
report. We expect to submit our next report by March 8, 1979.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

7901250156

58-390/391 5

B019
5/11