

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

APR 18 1979  
79 APR 20 A10: 01

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFFECTIVE PHILLIPS SELF-  
DRILL CONCRETE ANCHORS - NCR 1433R - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
McKensie Thomas on March 19, 1979. Enclosed is our first interim  
report. We expect to submit our next report by June 26, 1979.

If you have any questions concerning this matter, please get in touch  
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,



J. E. Gilleland  
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

7905140490

B019  
S/11

790122