

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
500C Chestnut Street Tower II

JUN 04 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

REGULATORY DOCKET FILE COPY

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - PILES SUPPORTING ERCW PIPE  
SLAB NOT DRIVEN TO DRAWING REQUIREMENTS - NCR CDB 79-3 - FIRST INTERIM  
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
McKensie Thomas on May 4, 1979, in accordance with 10 CFR 50.55(e).  
Enclosed is our first interim report. We expect to submit our next  
report by December 3, 1979.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland  
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

7906130330

B019  
5/1/1