

7E HQS

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

MAY 29 1979

79 MAY 30 4 8:51

USNRC REGION
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - POSSIBLE UNCONSERVATIVE
PRESSURIZER RELIEF AND SAFETY LINE BLOWDOWN ANALYSIS - NCR CWB
78-2 - FIFTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE
inspector, J. K. Rausch, on May 5, 1978. Interim reports
were submitted on June 1, 1978, July 31, 1978, February 8,
1979, and April 23, 1979.

TVA is waiting for Westinghouse to complete a detailed review
of the nozzle loads on the pressurizer and pressurizer relief
tank nozzles. We expect to submit our next report by
July 18, 1979.

If you have any questions concerning this matter, please get
in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,



J. E. Gilleland
Assistant Manager of Power

cc: Mr. John G. Davis, Acting Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

B019
S/10

79061 40 378