79044/390-79038/391

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

Hradgters.

August 1, 1979

REGULATORY DOCKET FILE COPY

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - MISSING SUPPORT FOR AUXILIARY FEEDWATER PUMP TRIP AND THROTTLE VALVE - NCR MEB 79-36 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector T. Donat on June 6, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our final report. This deficiency was reported for Sequoyah Nuclear Plant as NCR MEB 79-35.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

M. Mills, Manager

Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555