

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

August 20, 1979

REGULATORY DOCKET FILE COPY

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - ORIFICE FLANGES NOT MEETING
SPECIFICATIONS - NCR WB-M-79-06 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. Thomas on May 16, 1979, in accordance with 10 CFR 50.55(e).
Our first interim report was submitted on June 15, 1979. Enclosed
is our second interim report. We expect to submit our next report
by November 16, 1979.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

7908290426

Boia
S. 11