

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 31, 1980

US NRC
DISTRIBUTION SERVICES
BRANCH

1980 NOV 6 PM 2 45

RECEIVED DISTRIBUTION
SERVICES UNIT

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - QA BREAKDOWN, FAULTY FILLET WELDS -
NCR 2111R - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
R. W. Wright on February 20, 1980, in accordance with 10 CFR 50.55(e).
Interim reports were provided on March 19, May 6, and August 8, 1980.

TVA is continuing to reinspect fillet welds and repair those that are
found to be deficient. We expect to provide additional information by
February 6, 1981.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S/10

8011070455

5