

80-011-03L-


400 Chestnut Street Tower II

December 15, 1980

80-019-03L-

80-017-03L-

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 AND WATTS BAR NUCLEAR PLANT UNITS 1 AND 2
- DEFECTIVE REACTOR VESSEL UPPER INTERNALS GUIDE TUBE SUPPORT PINS -
NCR SQN NEB 8006 AND NCR WBN NEB 8001 - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. J. Gouge on March 24, 1980, in accordance with 10 CFR 50.55(e). Interim reports were submitted on April 23, July 24, and September 10, 1980. We expect to submit our next report by February 24, 1981.

TVA has not yet completed review of Westinghouse's report on their evaluation of the guide tube pins.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

5019
5/10

8103030749

S