

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 21, 1981

WBRD-50-390/81-36

WBRD-50-391/81-35

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - ANCHOR BOLTS INSTALLED NOT IN ACCORDANCE WITH SPACING SPECIFICATIONS - WBRD-50-390/81-36, WBRD-50-391/81-35 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on March 31, 1981, in accordance with 10 CFR 50.55(e) as NCR SWP 8106. Our first interim report was submitted on April 30, 1981.

TVA has determined that the description of the deficiency previously filed was not adequate in describing the nonconforming condition. A more detailed interim report, including the full scope and description of the nonconforming condition and corrective actions, will be transmitted to your office by June 4, 1981.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/0

5
81 05270444

An Equal Opportunity Employer