

CENTRAL FILES

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II, GEORGE
USNRC REGION II

January 6, 1981

81 JAN 9 9:49

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-21 - RII:JPO 50-328,
~~390, -391~~, -438, -439, -566, AND -567 - SEQUOYAH UNIT 2, WATTS BAR,
BELLEFONTE, AND YELLOW CREEK NUCLEAR PLANTS - RESPONSE TO BULLETIN

The subject letter dated November 6, 1980, transmitted IE Bulletin 80-21 on valve yokes supplied by Malcolm Foundry Company, Inc. TVA is in the process of obtaining assurance from valve suppliers that valves supplied under their contracts with TVA do not contain parts made by Malcolm Foundry. So far no valves have been found which have such parts. We expect to submit our final report before fuel loading for Sequoyah unit 2 and by May 28, 1981, for Watts Bar, Bellefonte, and Yellow Creek.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Division of Reactor Construction
Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGISTRATION SERVICES UNIT

1981 JAN 16 AM 10 47

US NRC DISTRIBUTION SERVICES BRANCH

8101210 239