

Central File
JAN 9 PM 1 08
U.S. NUCLEAR REGULATORY COMMISSION
OPERATIONS INSPECTION SERVICE
BRANCH

400 Chestnut Street Tower II

JAN 5 AM 10:04

December 30, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

~~OFFICE OF INSPECTION AND ENFORCEMENT~~ BULLETIN 80-23 - RII:JPO 50-328,
390, -391, -438, -439, -566, -567 SEQUOYAH UNIT 2, WATTS BAR, BELLEFONTE, AND
YELLOW CREEK NUCLEAR PLANTS

In response to your letter dated November 14, 1980, which transmitted IE Bulletin 80-23 on Failures of Solenoid Valves Supplied by Valcor Engineering Corporation, we have completed preliminary investigations. The preliminary investigations indicate that Tennessee Valley Authority (TVA) does not use Valcor solenoid valves having part numbers V70900-21-1 or -3. TVA is awaiting information from NSSS vendors for valves used on package components. We will provide you with further information before fuel loading for Sequoyah unit 2 and by March 31, 1981, for Watts Bar, Bellefonte, and Yellow Creek.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Director, Division of Reactor
Operations Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

70
2

810127003Q

Q