

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

MAR 16 1979

~~Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303~~

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT INSTALLATION OF SEISMIC
PIPE HANGER ANCHORS - NCR CAQR M-31 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Bruce Cochran on December 20, 1978. An interim report was submitted
on January 19, 1979. We expect to furnish our next report by
May 15, 1979.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

7903270531

8019
S/11

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

MAR 16 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT INSTALLATION OF SEISMIC
PIPE HANGER ANCHORS - NCR CAQR M-31 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Bruce Cochran on December 20, 1978. An interim report was submitted
on January 19, 1979. We expect to furnish our next report by
May 15, 1979.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

7903270531

B019
S/11