

Office Memorandum • UNITED STATES GOVERNMENT

TO : H. L. Price, Director
Division of Licensing and Regulation

DATE: FEB 7 1958

FROM : Marvin M. Mann, Assistant Director, Compliance
Division of Inspection *M*

SUBJECT: THE MARTIN COMPANY, LICENSE NOS. C-3147, C-3508 and C-3572, 10 CFR 40

mbol: INS:CCP

Attached is a copy of the inspection report, prepared by the New York Operations Office Inspection Division, concerning activities of the subject licensee.

Information gathered during inspection shows that the licensee was in non-compliance with the following:

- 10 CFR 20.203(f)(2) Caution signs, labels, and signals
(License No. C-3147)
Container containing 6.6 lbs. of UO₂ sources was not labeled as specified in this section.
(Par. 18 of report.)

It is suggested that a letter be addressed to the licensee to inform him of the above non-compliance items and request that appropriate action be taken to correct or overcome these deficiencies. When corrective action has been completed on this matter, please furnish the office that conducted the inspection with copies of pertinent correspondence and these items will be checked during the next regularly scheduled inspection.

A summary of this case will be included in the February report to the Office of the General Manager.

A copy of this memorandum and the enclosure has been furnished the Office of the General Counsel.

Enclosure
Cpy Rpt Dtd 1-15-58

Alm