

**RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - January 2008**

<b>ADAMS ML # or Event #</b>	<b>Event Date</b>	<b>Notification Date</b>	<b>Licensee</b>	<b>License Number</b>	<b>Reporting Requirement</b>	<b>Event Description</b>	<b>Assigned Inspector</b>	<b>Review Status</b>
ML073650249	11/21/07	12/27/07	Acuren	42-32443-01	10 CFR 34.101	Radiography source could not be retracted into the fully shielded position	Razo	Open
ML073600899	8/24/07	9/24/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Open
ML072670492	12/20/07	12/20/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Open
ML072980686	10/21/07	10/22/07	CONAM Inspection	12-16559-02	This event was not reportable	Radiography truck was involved in a traffic accident	Thompson	Open
ML071650343	9/1/07	9/2/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Donovan	Open
ML073300631	10/4/07	11/19/07	Schlumberger	42-00090-03	10 CFR 20.2201	A missing fluid density meter containing cesium-137	Leonardi	Open
ML080100169	12/23/07	1/10/08	Haliburton	42-01069-07	10 CFR 39.77	Well logging source abandonment	Gaines	Open
43769	11/3/07	11/19/07	Kakivik Asset Management	50-27667-01	10 CFR 30.50	Radiography camera source fails to retract to fully shielded position	Munoz	Open
ML073201184	10/27/07	11/15/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Leonardi	Open
43721	10/12/07	10/12/07	Thomas, Dean, & Hoskings	25-17579-01	10 CFR 30.50	Portable nuclear gauge damaged at temporary job site	Munoz	Open
ML072530266	9/5/07	9/7/07	Cogema	SUA-1341	License Condition	Report of an excursion of a perimeter ore zone monitor well	Evans	Open

**RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - January 2008**

<b>ADAMS ML # or Event #</b>	<b>Event Date</b>	<b>Notification Date</b>	<b>Licensee</b>	<b>License Number</b>	<b>Reporting Requirement</b>	<b>Event Description</b>	<b>Assigned Inspector</b>	<b>Review Status</b>
ML071900434	7/5/07	7/6/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Razo	Open
ML072350490	8/7/07	8/21/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Razo	Open
43508	5/22/07	7/20/07	Oceaneering International	LA-7396-L01	10 CFR 20.2202	Possible personnel radiation exposure, greater than 5 rem	Thompson	Open
42722	7/22/06	7/22/06	TEAM Industrial Services	42-32219-01	10 CFR 30.50	Radiography camera source unable to be retracted to the fully shielded position	Leonardi	Open
ML072410216	8/23/07	8/24/07	FMRI	SMB-911	10 CFR 2203	Report of concentrations of radioactive material exceeding license limits	Evans	Open
ML071930547	6/26/07	7/5/07	Watts Constructors	53-27792-01	10 CFR 20.2201	Missing portable nuclear gauge containing cesium-137 and americium-241	Brown	Open
ML071650343	6/14/07	6/14/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Brown	Open
060663	9/1/06	9/1/06	General Electric Company	SNM-0960	License Condition	Removable surface contamination exceeding regulatory limits	Garcia	Open
40897	7/24/04	7/27/04	San Onofre	DPR-13	10 CFR 72.75	Advanced horizontal storage seismic restraint bolt failure	Atwater	Closed (report attached)
ML063470060	11/6/06	11/6/06	Rancho Seco	SNM-2510	10 CFR 72.75	Class "C" fuel assemblies potentially having flaws greater than requirements	Atwater	Closed (report attached)
ML071790044	5/22/07	6/26/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Razo	Closed (report attached)

**RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - January 2008**

<b>ADAMS ML # or Event #</b>	<b>Event Date</b>	<b>Notification Date</b>	<b>Licensee</b>	<b>License Number</b>	<b>Reporting Requirement</b>	<b>Event Description</b>	<b>Assigned Inspector</b>	<b>Review Status</b>
ML080150320	6/28/07	6/28/07	Pathfinder Energy Services	17-27623-01	10 CFR 39.77	Well logging source abandonment	Razo	Closed (report attached)
ML072400066	8/27/07	8/28/07	Micron Technology Inc.	IDA-227	10 CFR 20.2201	Loss of nine static eliminators containing polonium-210	Gersey	Closed (report attached)
ML07300988	9/28/07	11/5/07	Century Geophysical Corporation	35-04017-04	10 CFR 39.77	Well logging source abandonment	Donovan	Closed (report attached)
ML072050446	7/20/07	7/20/07	Mattingly Testing Services	25-21479-01	10 CFR 34.101	Radiography camera source stuck in guide tube	Donovan	Closed (report attached)
ML072280037	8/12/07	8/15/07	Pathfinder Energy Services	17-27623-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML072350456	8/14/07	8/14/07	Precision Energy Services	42-26891-01	10 CFR 39.77	Well logging source abandonment	Razo	Closed (report attached)