

USNRC REGION I
ATLANTA, GEORGIA

19 JUN 18 09:19

P. O. Box 529100
Miami, Florida 33152

IEEA



FLORIDA POWER & LIGHT COMPANY

June 15, 1979
L-79-165

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
Docket 50-389
IE Bulletin 78-06

The following information supplements our August 1, 1978 (L-78-253) response to IE Bulletin 78-06. Florida Power & Light Company (FPL) has determined that Cutler-Hammer Type M relays with DC coils are not in use or planned for use in safety related systems in St. Lucie Unit 2.

This completes FPL action in response to IE Bulletin 78-06.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU:TCG:cf

cc: Harold F. Reis, Esquire

AOI
2
462 297
7 907 3 10 199
100/4 Q

OFFICIAL COPY
PEOPLE ... SERVING PEOPLE