



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

February 5, 2008

MEMORANDUM TO: Michele L. Burgess, Health Physicist (MS-8F5)
Medical Safety & Events Assessment Branch
Division of Materials Safety & State Agreements

FROM: Vivian H. Campbell, Chief */RA/*
Nuclear Materials Safety Branch-A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for February 2008. In addition, enclosed are the licensee event report evaluation forms for the events closed in January 2008, detailing Region IV's response to these events.

Enclosures:

1. February 2008 RIV DNMS Licensee Event Reports Summary Table
2. LER evaluation forms for RIV events closed in January 2008

bcc w/enclosures (Report):

EECollins
LDWert
CLCain
VHCampbell
JEWhitten
DBSpitzberg
LER File

SUNSI review completed: ADAMS: Yes Initials: JLT

Publicly Available Non-Sensitive

DOCUMENT NAME: s:\dnms!\nmib\LERs\2008\02-2008.doc

RIV:DNMS:NMS-A	C:NMS-A
JLThompson	VHCampbell
<i>/RA/</i>	<i>/RA/</i>
2/05/2008	2/05/2008

OFFICIAL RECORD COPY T=Telephone E=E-mail F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - FEBRUARY 2008

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
ML080240230	1/20/08	1/22/08	Pathfinder Energy Services	17-27623-01	10 CFR 39.77	Well logging source abandonment	Gaines	Open
ML080250414	1/17/08	1/17/08	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Munoz	Open
ML080280081	1/28/08	1/28/08	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Brown	Open
ML080300558	1/27/08	1/28/08	Weatherford International	42-26891-01	10 CFR 39.77	Well logging source abandonment	Razo	Open
ML072550604	9/1/07	9/2/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Donovan	Open
ML073300631	10/4/07	11/19/07	Schlumberger	42-00090-03	10 CFR 20.2201	A missing fluid density meter containing cesium-137	Leonardi	Open
ML080100169	12/23/07	1/10/08	Haliburton	42-01069-07	10 CFR 39.77	Well logging source abandonment	Gaines	Open
43769	11/3/07	11/19/07	Kakivik Asset Management	50-27667-01	10 CFR 30.50	Radiography camera source fails to retract to fully shielded position	Munoz	Open
ML073201184	10/27/07	11/15/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Leonardi	Open
ML072530266	9/5/07	9/7/07	Cogema	SUA-1341	License Condition	Report of an excursion of a perimeter ore zone monitor well	Evans	Open

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - FEBRUARY 2008

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
ML072350490	8/7/07	8/21/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Razo	Open
42722	7/22/06	7/22/06	TEAM Industrial Services	42-32219-01	10 CFR 30.50	Radiography camera source unable to be retracted to the fully shielded position	Leonardi	Open
ML072410216	8/23/07	8/24/07	FMRI	SMB-911	10 CFR 2203	Report of concentrations of radioactive material exceeding license limits	Evans	Open
ML071930547	6/26/07	7/5/07	Watts Constructors	53-27792-01	10 CFR 20.2201	Missing portable nuclear gauge containing cesium-137 and americium-241	Brown	Open
ML071650343	6/14/07	6/14/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Brown	Open
060663	9/1/06	9/1/06	General Electric Company	SNM-0960	License Condition	Removable surface contamination exceeding regulatory limits	Garcia	Open
ML072670492	12/20/07	12/20/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
43508	5/22/07	7/20/07	Oceaneering International	LA-7396-L01	10 CFR 20.2202	Possible personnel radiation exposure, greater than 5 rem	Thompson	Closed (report attached)
ML073600899	8/24/07	9/24/07	Schlumberger	42-00090-03	10 CFR 39.77	Well logging source abandonment	Thompson	Closed (report attached)
ML072980686	10/21/07	10/22/07	CONAM Inspection	12-16559-02	This event was not reportable	Radiography truck was involved in a traffic accident	Thompson	Closed (report attached)
ML071900434	7/5/07	7/6/07	Baker Hughes Inteq	17-27437-01	10 CFR 39.77	Well logging source abandonment	Razo	Closed (report attached)

