

February 13, 2008

Mr. Charles G. Pardee
Chief Nuclear Officer
AmerGen Energy Company, LLC
4300 Winfield Road
Warrenville IL 60555

SUBJECT: ERRATA TO CLINTON POWER STATION, NRC INTEGRATED INSPECTION
REPORT 05000461/2007004

Dear Mr. Pardee:

On November 6, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued integrated Inspection Report 05000461/2007004 (ML073100335) for your Clinton Power Station, Unit 1. An inspection sample for verifying Radiation Safety Performance Indicators was inadvertently omitted in the original report. The enclosed errata contains the omitted inspection sample, and should be inserted as Page 19(a) where appropriate into integrated Inspection Report 05000461/2007004.

Sincerely,

/RA/

Mark A. Ring, Chief
Branch 1
Division of Reactor Projects

Docket No. 50-461
License No. NPF-62

Enclosure: Errata to Inspection Report No. 05000461/2007004

DISTRIBUTION:
See next page

Letter to C. Pardee from M. Ring dated February 13, 2008

SUBJECT: ERRATA TO CLINTON POWER STATION, NRC INTEGRATED INSPECTION
REPORT 05000461/2007004

cc w/encl: Site Vice President - Clinton Power Station
Plant Manager - Clinton Power Station
Regulatory Assurance Manager - Clinton Power Station
Chief Operating Officer and Senior Vice President
Senior Vice President - Midwest Operations
Senior Vice President - Operations Support
Vice President - Licensing and Regulatory Affairs
Director - Licensing and Regulatory Affairs
Manager Licensing - Clinton, Dresden and Quad Cities
Associate General Counsel
Document Control Desk - Licensing
Assistant Attorney General
State Liaison Officer
Illinois Emergency Management Agency
Chairman, Illinois Commerce Commission
Illinois Emergency Management Agency

February 13, 2008

Mr. Charles G. Pardee
Chief Nuclear Officer
AmerGen Energy Company, LLC
4300 Winfield Road
Warrenville IL 60555

SUBJECT: ERRATA TO CLINTON POWER STATION, NRC INTEGRATED INSPECTION
REPORT 05000461/2007004

Dear Mr. Pardee:

On November 6, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued integrated Inspection Report 05000461/2007004 (ML073100335) for your Clinton Power Station, Unit 1. An inspection sample for verifying Radiation Safety Performance Indicators was inadvertently omitted in the original report. The enclosed errata contains the omitted inspection sample, and should be inserted as Page 19(a) where appropriate into integrated Inspection Report 05000461/2007004.

Sincerely,

/RA/

Mark A. Ring, Chief
Branch 1
Division of Reactor Projects

Docket No. 50-461
License No. NPF-62

Enclosure: Errata to Inspection Report No. 05000461/2007004

DISTRIBUTION:
See next page

DOCUMENT NAME: G:\CLIN\CLIN 2007 004 ERRATA.DOC

☐ Publicly Available

☐ Non-Publicly Available

☐ Sensitive

☐ Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	E	RIII		RIII		RIII	
NAME	MRing:cms							
DATE	2/13/2008							

OFFICIAL RECORD COPY

Letter to C. Pardee from M. Ring dated February 13, 2008

SUBJECT: ERRATA TO CLINTON POWER STATION, NRC INTEGRATED INSPECTION
REPORT 05000461/2007004

DISTRIBUTION:

TEB

RAG1

SPS1

MMT

RidsNrrDirslrib

MAS

KGO

JKH3

RML2

SRI Clinton

CAA1

LSL (electronic IR's only)

C. Pederson, DRP (hard copy - IR's only)

DRSIII

DRPIII

PLB1

TXN

ROPreports@nrc.gov (inspection reports, final SDP letters, any letter with an IR number)

ERRATA TO NRC INTEGRATED INSPECTION REPORT 05000461/2007004

In Inspection Report 05000461/2007004, insert the following as Page 19(a), under Section 4OA1:

4OA1 Performance Indicator Verification (71151)

Cornerstone: Occupational Radiation Safety

a. Inspection Scope

The inspectors reviewed the licensee's determination of Performance Indicator (PI) for the Occupational Radiation Safety Cornerstone (Occupational Exposure Control Effectiveness) to verify that the licensee accurately determined these performance indicators and had identified all occurrences required by these indicators. Specifically, the inspectors reviewed the licensee's Corrective Action Program documents for the 3rd and 4th quarters of CY 2006 and the 1st and 2nd quarters of CY 2007 Occupational Exposure performance indicator data to ensure that there were no PI occurrences that were not identified by the licensee. Additionally, as part of plant walkdowns (Section 2OS1.2), the inspectors selectively examined the adequacy of posting and controls for locked high dose rates (HRAs), to verify the current Occupational Exposure Control Effectiveness performance indicator. The inspectors interviewed members of the licensee's staff who were responsible for performance indicator data acquisition, verification and reporting, to verify that their review and assessment of the data was adequate. This represented one sample.

b. Findings

No findings of significance were identified.