

WATTS BAR NUCLEAR PLANT

TECHNICAL INSTRUCTION

TI-50B

ASME SECTION XI PRESERVICE  
INSPECTION PROGRAM

UNIT 2

CURRENT REVISION LEVEL 5

Prepared By Dave De Tullio

Revised By Jeff Goulart

Submitted By Jinda J. Smith  
for Supervisor

PORC Review Date 10/17/83

Approved By [Signature]  
Superintendent

Date Approved 10/17/83

- 1C Document Control Unit, 1520 CST2-C
- 1U NRC
- 1C Nuclear Safety Review Staff
- 1C Plant Master File
- Plant Superintendent
- Asst. Plant Supt. (Operations)
- Asst. Plant Supt. (Maintenance)
- Adm. Svs. Supervisor
- Asst. Mechanical Maint. Sup.
- Chemical Laboratory
- Chemical Unit Supervisor
- 1C Chief, Nuclear Training Branch
- Compliance Unit
- DPSO-WBN
- Document Control Supervisor
- Electrical Maint. Supervisor
- Electrical Shop
- 1C Engineering Supervisor
- 1C Field Services Supervisor
- 1C Health Physicist
- Health Physics Laboratory
- 1C Instrument Engineer
- 1C Instrument Maint. Supervisor
- 1C Instrument Shop
- Janitor & Labor Supervisor
- Management Svs. Supervisor
- 1C Mechanical Maint. Supervisor
- 1C Mechanical Unit Supervisor
- 1C Operations Supervisor
- OPQA - Plant Coordinator
- Plant Services Supervisor
- Plant Training Officer
- 1U Plant Training Shift Engineer
- 1C Power Stores Unit Supervisor
- Preop Test Supervisor
- Public Safety
- QA Manager, QA and Audit Staff
- 1C Quality Assurance Supervisor
- Reactor Unit Supervisor
- Safety Engineer
- 1C Shift Engineer's Office
- Stationary Equipment Group
- Technical Support Center
- 1C Unit 1 Control Room
- 1C Unit 2 Control Room
- 1U Supv. Reactor Systems Group-C
- 1C Baseline Inservice Inspection Group-
- 1C Programs and Procedures Section-C
- 1C Mech. Maint. Shop Office
- 1C DCU-B, Const. - WBNP

Last page of this instruction: 108

OS/6

8311280332 831121  
PDR ADOCK 05000390  
Q PDR