NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION					
(10-2003) 10 CFR 2.201					
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
Foerster Testing 209 8 th Street W.			USNRC Region IV		
Brookings, South Dakota 57006			611 Ryan Plaza Drive Arlington, Texas 76011-4005		
			Ariington, Texas 76011-4005		
REPORT NUMBER(S)	030-37498/2008001	İ			
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-37498		40-29268-01	*	2/20/2008	
LICENSEE:					
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)					
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date					
Title	Print	еа ічате		Signature	Date
LICENSEE'S REPRESENTATIVE					/ ,
NRC INSPECTOR	Robert A. Brown	1	Color	4-Pu	3/13/08