NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (10-2003)						
10 CFR 2.201	SAFETY INS	PECTION REPORT	AND COMPLIANCE	EINSPECTIO	ON	
LICENSEE/LOCATION INSPECTED:     Comprehensive Cardiology Consultants, PA     1205 Langhorne Newtown Road     Langhorne, Pennsylvania 19047			2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415			
REPORT Nos 2008-001		LA LIGENCE NUMBERO	DED(C) IS DATE(C) OF INC		VOE MICREOTI	
3. DOCKET NUMBER(S) 030-37418		4. LICENSE NUMBER(S) 37-31225-01		5. DATE(S) OF INSPECTION February 21 & March 13, 2008		
LICENSEE:		37-3	1220-01	1 ebi	uary 21 & IVI	31071 13, 2000
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X						
Licensee's Statement of Corrective Actions for Item 4, above.  I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date  LICENSEE'S REPRESENTATIVE						
NRC INSPECTOR	L. Roldán & E. Ul	llrich	L. Polda.	n/54	Ulil	3/12/08