

NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201 **U.S. NUCLEAR REGULATORY COMMISSION**

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Temple University 3307 North Broad Street, Room B-49 Philadelphia, Pennsylvania 19140		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2008001			
3. DOCKET NUMBER(S) 030-02963	4. LICENSE NUMBER(S) 37-00697-31	5. DATE(S) OF INSPECTION March 3 - 7, 2008	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 35.615(f)(3) requires an authorized user (AU) and an authorized medical physicist (AMP) to be physically present throughout all patient treatments involving a gamma stereotactic radiosurgery (GSR) unit.

Contrary to the above, on March 7, 2008, at Temple University, an AMP did not maintain physical presence throughout a patient treatment involving a GSR unit. Specifically, the AMP briefly left the patient console room for less than one minute, during which time the AMP quickly walked approximately 35 feet down a hallway, entered a separate break room to retrieve a form, and then returned to the GSR treatment console.

This is a Severity Level IV violation (Supplement VI). **EA 08-096**

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	ROBERT E. PERZOLI		3-28-08
NRC INSPECTOR	Randolph C. Ragland, Jr.		3/27/2008

SUNSI Review Completed By: /RA/ R. C. Ragland, Jr. Public Non-Sensitive