

NRC INSPECTION MANUAL

DIRS

Change Notice 08-012

DELETED:		TRANSMITTED:	
<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. _____	_____	IP 65001.04	04/18/08
2. _____	_____	IP 65001.06	04/18/08
3. _____	_____	IP 73757	04/18/08
4. IP 81401	06/13/85	_____	_____
5. IP 81403	06/13/85	_____	_____
6. IP 81910	02/19/91	_____	_____
7. IP 81911	02/19/91	_____	_____
8. IP 81912	02/19/91	_____	_____
9. IP 81913	02/19/91	_____	_____
10. IP 81914	02/19/91	_____	_____
11. IP 81915	02/19/91	_____	_____
12. IP 81916	02/19/91	_____	_____
13. IP 81917	02/19/91	_____	_____
14. IP 81918	02/19/91	_____	_____
15. IP 81919	02/19/91	_____	_____
16. IP 81920	02/19/91	_____	_____
17. IP 81921	02/19/91	_____	_____
18. IP 81922	02/19/91	_____	_____

19. IP 81923	02/19/91	_____	_____
20. IP 81924	02/19/91	_____	_____
21. IP 81925	02/19/91	_____	_____
22. IP 81926	02/19/91	_____	_____
23. IP 81927	02/19/91	_____	_____
24. IP 81928	02/19/91	_____	_____
25. IP 81929	02/19/91	_____	_____
26. IP 81930	02/19/91	_____	_____
27. IP 81931	02/19/91	_____	_____
28. IP 81932	02/19/91	_____	_____
29. IP 81933	03/18/91	_____	_____
30. IP 81934	03/18/91	_____	_____
31. IP 81935	02/19/91	_____	_____

TRAINING: None

REMARKS: IP 65001.04 (Inspection of ITAAC-Related Installation of Pipe Supports and Restraints) is issued to support the Inspections, Tests, Analyses, and Acceptance Criteria (ITAAC) related New Reactor Construction Inspections under 10 CFR Part 52.

IP 65001.06 (Inspection of ITAAC-Related Installation of Mechanical Components) is issued to support the ITAAC related New Reactor Construction Inspections under 10 CFR Part 52.

IP 73757 (Part 52, Preservice Inspection - Data Review and Evaluation) is issued to support inspections of operational programs described in IMC 2504, "Construction Inspection Program - Non-ITAAC Inspections."

The following inspection procedures have been deleted. These security inspection procedures are being cancelled based on their incorporation into other inspection procedures which were created to reflect new security requirements since 9/11, modifications to inspection techniques, and lessons learned:

IP 81401 (Plans, Procedures and Reviews)
IP 81403 (Receipt of New Fuel at Reactor Facilities)
IP 81910 (Alarm Stations)
IP 81911 (Assessment)
IP 81912 (Badge Control)
IP 81913 (Communications)
IP 81914 (Duress Alarms)
IP 81915 (EECP Machine Performance - Explosive Detectors)
IP 81916 (EECP Machine Performance - Metal Detectors)
IP 81917 (EECP Machine Performance - X-Ray)
IP 81918 (Emergency Power Supply)
IP 81919 (Interior Alarms)
IP 81920 (Intrusion Detection System)
IP 81921 (Isolation Zone)
IP 81922 (Keys, Locks, and Combinations)
IP 81923 (Lighting)
IP 81924 (MAA Barriers)
IP 81925 (Personnel Searches)
IP 81926 (Preventative Maintenance)
IP 81927 (Protected Area Barriers)
IP 81928 (Protected Area Housekeeping)
IP 81929 (Strategic Special Nuclear Material Exit Searches)
IP 81930 (Tactical Response Team Exercises)
IP 81931 (Vehicle Barriers)
IP 81932 (Vehicle Escorts)
IP 81933 (Vehicle Searches)
IP 81934 (Warehouse Searches)
IP 81935 (Weapons Qualification)

DISTRIBUTION: Standard

END