

**NEWARK BETH ISRAEL**  
**MEDICAL CENTER**  
*An affiliate of the Saint Barnabas Health Care System*

RONALD J. DEL MAURO  
President and Chief Executive Officer  
Saint Barnabas Health Care System

NW1581

RECEIVED  
REGION 1  
2008 APR 21 AM 8:52

April 16, 2008

United States Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19405

03020802

Re: License No. 29-00102-07  
Control No. 141897 *NW*


Dear Sir or Madam:

As stated in the correspondence dated February 5, 2008 the two nuclear gamma cameras located in the Cardiac Non-Invasive Laboratory rooms designated as Nuclear Room # 1 and Nuclear Room # 2 were relocated to the main Nuclear Medicine Department. A close out survey (enclosure # 1) and wipe test (enclosure # 2) were performed once the rooms were vacated; copies of the results are enclosed.

Radioactive materials are no longer used in the areas once designated as Nuclear Room # 1 and Nuclear Room # 2 in the Cardiac Non-Invasive Laboratory. The licensee would like to amend Radioactive License No. 29-000102-07 and remove the two rooms from the license.

If you have any additional questions regarding this correspondence, please contact Ms. Constance Sorensen, Director of Nuclear Medicine at (973) 926-7888.

Sincerely:



Kenneth L. Tyson  
Senior Vice President-Operations

Enclosures (2)

142325

NMSS/RGN1 MATERIALS-002  
REF. 141897

201 LYONS AVENUE AT OSBORNE TERRACE ■ NEWARK, NEW JERSEY 07112 ■ (201) 926-7000



Newark Beth Israel Medical Center

Nuclear Medicine Department

Newark, New Jersey

Daily Area Monitoring: 10765

Group : NUCLEAR DEPT

Dt 02-01-2008 Tm: 16:25 Tech: ALBERT BAQUIRAN  
 Inst: LUDLUM 3 PANCAK Serial#: 111450  
 Manuf: LUDLUM Next Cal.: 12-07-2008  
 Trg Lmt: 0.50 mR/hr Eff: N/A  
 Bkg: .00 mR/hr

Areas	mR/hr
B, SINK	0.05
B, TABLE	0.05
B, WASTE	0.05
A, REINJ	0.03
A, SINK	0.03
A, TABLE	0.03
A. L-BLOCK	0.05
A, TREADM	0.08
A, FLOOR	0.03
A, WASTE	0.08
B, TREADM	0.05
B, FLOOR	0.03
C, TREADMILL	0.05
DEPT, BKGD	---
DOSE CALI	---
FUME HOOD	---
HL, BKGD	---
HL, FLOOR	---
HL, SAFE	---
HL, SINK	---
HL, SYRING	---
INJ WASTE	---
INJECT RM	---
L-BLOCK	---
NON-WASTE	---
R1, INJECT	---
R1, WASTE	---
R2, INJECT	---
R2, WASTE	---
R3, INJECT	---
R3, WASTE	---
R4, INJECT	---
R4, WASTE	---
R5, INJECT	---
R5, WASTE	---
REMOTE ST	---
STRECHER	---
IC WASTE	---
TOILET	---

ENCLOSURE #1

Newark Beth Israel Medical Center

Nuclear Medicine Department

Newark, New Jersey

Daily Area Monitoring: 10765

Group : NUCLEAR DEPT

Dt 02-01-2008 Tm: 16:25 Tech: ALBERT BAQUIRAN

Inst: LUDLUM 3 PANCAK Serial#: 111450

Manuf: LUDLUM Next Cal.: 12-07-2008

Trg Lmt: 0.50 mR/hr Eff: N/A

Bkg: .00 mR/hr

Areas mR/hr

UNIT DOSE ---

**Values indicates that the test has exceeded the trigger limit**

Comment:CAMERA 1 AND 2 AREA CLOSED SURVEY

Newark Beth Israel Medical Center  
Nuclear Medicine Department  
Newark, New Jersey

Weekly Area Wipe Test: 1153

Group : NUCLEAR DEPT

Date: 02-02-2008 Tm: 14:15 Tech: HEMANT DESAI  
Instr: CAPTUS 3000 S#:  
Manuf: CAPINTEC Next Cal:  
Trg Lmt: 2000 DPM Efficiency: N/A  
Bkg: 0 DPM Wipe Area: 100 Sq.CM

Areas	DPM
B, SINK	316
B, TABLE	301
B, WASTE	460
A, REINJ	0
A, SINK	129
A, TABLE	92
A. L-BLOCK	75
A, TREADM	64
A, FLOOR	90
A, WASTE	83
B, TREADM	266
B, FLOOR	126
C, TREADMILL	123
DEPT, BKGD	0
DOSE CALI	61
FUME HOOD	0
HL, BKGD	43
HL, FLOOR	46
HL, SAFE	50
HL, SINK	16
HL, SYRING	7
INJ WASTE	0
INJECT RM	27
L-BLOCK	0
NON-WASTE	0
R1, INJECT	0
R1, WASTE	55
R2, INJECT	83
R2, WASTE	40
R3, INJECT	47
R3, WASTE	35
R4, INJECT	24
R4, WASTE	40
R5, INJECT	0
R5, WASTE	25
REMOTE ST	---
STRECHER	38
TC WASTE	0
TOILET	56
UNIT DOSE	32

Comment : FINAL WIPES FOR CAMERA 1 & 2, CNIL

**Bold** Values indicate that the TRIGGER LIMIT has been exceeded.

ENCLOSURE # 2

This is to acknowledge the receipt of your letter/application dated

4/16/2008, and to inform you that the initial processing which includes an administrative review has been performed.

ARMAS. 29-00102-07 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 142325.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.