

NEWARK BETH ISRAEL
MEDICAL CENTER
An affiliate of the Saint Barnabas Health Care System

RONALD J. DEL MAURO
President and Chief Executive Officer
Saint Barnabas Health Care System

NW1581

RECEIVED
REGION 1
2008 APR 21 AM 8:52

April 16, 2008

United States Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19405

03020802

Re: License No. 29-00102-07
Control No. 141897 *NW*


Dear Sir or Madam:

As stated in the correspondence dated February 5, 2008 the two nuclear gamma cameras located in the Cardiac Non-Invasive Laboratory rooms designated as Nuclear Room # 1 and Nuclear Room # 2 were relocated to the main Nuclear Medicine Department. A close out survey (enclosure # 1) and wipe test (enclosure # 2) were performed once the rooms were vacated; copies of the results are enclosed.

Radioactive materials are no longer used in the areas once designated as Nuclear Room # 1 and Nuclear Room # 2 in the Cardiac Non-Invasive Laboratory. The licensee would like to amend Radioactive License No. 29-000102-07 and remove the two rooms from the license.

If you have any additional questions regarding this correspondence, please contact Ms. Constance Sorensen, Director of Nuclear Medicine at (973) 926-7888.

Sincerely:



Kenneth L. Tyson
Senior Vice President-Operations

Enclosures (2)

142325

NMSS/RGN1 MATERIALS-002
REF. 141897

201 LYONS AVENUE AT OSBORNE TERRACE ■ NEWARK, NEW JERSEY 07112 ■ (201) 926-7000



Newark Beth Israel Medical Center

Nuclear Medicine Department

Newark, New Jersey

Daily Area Monitoring: 10765

Group : NUCLEAR DEPT

Dt 02-01-2008 Tm: 16:25 Tech: ALBERT BAQUIRAN
 Inst: LUDLUM 3 PANCAK Serial#: 111450
 Manuf: LUDLUM Next Cal.: 12-07-2008
 Trg Lmt: 0.50 mR/hr Eff: N/A
 Bkg: .00 mR/hr

Areas	mR/hr
B, SINK	0.05
B, TABLE	0.05
B, WASTE	0.05
A, REINJ	0.03
A, SINK	0.03
A, TABLE	0.03
A. L-BLOCK	0.05
A, TREADM	0.08
A, FLOOR	0.03
A, WASTE	0.08
B, TREADM	0.05
B, FLOOR	0.03
C, TREADMILL	0.05
DEPT, BKGD	---
DOSE CALI	---
FUME HOOD	---
HL, BKGD	---
HL, FLOOR	---
HL, SAFE	---
HL, SINK	---
HL, SYRING	---
INJ WASTE	---
INJECT RM	---
L-BLOCK	---
NON-WASTE	---
R1, INJECT	---
R1, WASTE	---
R2, INJECT	---
R2, WASTE	---
R3, INJECT	---
R3, WASTE	---
R4, INJECT	---
R4, WASTE	---
R5, INJECT	---
R5, WASTE	---
REMOTE ST	---
STRECHER	---
IC WASTE	---
TOILET	---

ENCLOSURE #1

Newark Beth Israel Medical Center

Nuclear Medicine Department

Newark, New Jersey

Daily Area Monitoring: 10765

Group : NUCLEAR DEPT

Dt 02-01-2008 Tm: 16:25 Tech: ALBERT BAQUIRAN

Inst: LUDLUM 3 PANCAK Serial#: 111450

Manuf: LUDLUM Next Cal.: 12-07-2008

Trg Lmt: 0.50 mR/hr Eff: N/A

Bkg: .00 mR/hr

Areas mR/hr

UNIT DOSE ---

Bold Values indicates that the test has exceeded the trigger limit

Comment:CAMERA 1 AND 2 AREA CLOSED SURVEY

Newark Beth Israel Medical Center
Nuclear Medicine Department
Newark, New Jersey

Weekly Area Wipe Test: 1153

Group : NUCLEAR DEPT

Date: 02-02-2008 Tm: 14:15 Tech: HEMANT DESAI
Instr: CAPTUS 3000 S#:
Manuf: CAPINTEC Next Cal:
Trg Lmt: 2000 DPM Efficiency: N/A
Bkg: 0 DPM Wipe Area: 100 Sq.CM

Areas	DPM
B, SINK	316
B, TABLE	301
B, WASTE	460
A, REINJ	0
A, SINK	129
A, TABLE	92
A. L-BLOCK	75
A, TREADM	64
A, FLOOR	90
A, WASTE	83
B, TREADM	266
B, FLOOR	126
C, TREADMILL	123
DEPT, BKGD	0
DOSE CALI	61
FUME HOOD	0
HL, BKGD	43
HL, FLOOR	46
HL, SAFE	50
HL, SINK	16
HL, SYRING	7
INJ WASTE	0
INJECT RM	27
L-BLOCK	0
NON-WASTE	0
R1, INJECT	0
R1, WASTE	55
R2, INJECT	83
R2, WASTE	40
R3, INJECT	47
R3, WASTE	35
R4, INJECT	24
R4, WASTE	40
R5, INJECT	0
R5, WASTE	25
REMOTE ST	---
STRECHER	38
TC WASTE	0
TOILET	56
UNIT DOSE	32

Comment : FINAL WIPES FOR CAMERA 1 & 2, CNIL

Bold Values indicate that the TRIGGER LIMIT has been exceeded.

ENCLOSURE # 2

This is to acknowledge the receipt of your letter/application dated

4/16/2008, and to inform you that the initial processing which includes an administrative review has been performed.

ARMAS, 29-00102-07 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 142325.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.