POST-EXAM COMMENTS

(Green Paper)

Licensee Submitted Post-Exam Comments

[X] Attached

[] None

VIRGINIA ELECTRIC AND POWER COMPANY RICHMOND, VIRGINIA 23261

April 11, 2008

Mr. Victor McCree	Serial No. 08-0218
Acting Regional Administrator	SS&L/TJN R0
United States Nuclear Regulatory Commission	Docket Nos. 50-280
Region II	50-281
Sam Nunn Atlanta Federal Center	License Nos. DPR-32
61 Forsyth St., SW, Suite 23T85	DPR-37
Atlanta, Georgia 30303-8931	

VIRGINIA ELECTRIC AND POWER COMPANY SURRY POWER STATION UNITS 1 AND 2 WRITTEN/OPERATING LICENSE EXAMINATION COMMENTS

In accordance with NUREG-1021, Section ES-402, the following comments are submitted concerning the Reactor Operator and Senior Reactor Operator Initial Examinations administered at Surry in March and April 2008.

Written Exam:

Surry Power Station does not have any post exam comments related to the written exam administered on April 9, 2008.

Operating Exam:

ADMIN JPM G2.1.7 Quadrant Power Tilt Calculation

The number in the answer key for the N-44 Upper Tilt Calculation was listed as .9895. The correct answer should have been .9858. This was not a critical task in this JPM.

N-44 Upper Tilt calculation had a transposition error.

Recommendation: Replace .9895 with .9858 in answer key for the N-44 Upper Tilt Calculation.

ADMIN JPM G2.4.43 Transmit Report of Emergency to State and Local Governments

Item 5 of the transmittal form had the critical task listed as "Unit 1 reactor failed to trip. The reactor is now tripped (or words to this effect)".

After conferring with the Emergency Preparedness group, only notifying the State that the reactor failed to trip is required to meet the minimum requirements for this task (i.e. this is the minimum required for a satisfactory Performance Indicator). This evaluation criterion was subsequently identified in DNAP-2605 (Emergency Preparedness Performance Indicators). Attachment 2 of this procedure only requires a description of the event, which is meant to indicate the reason for entering the emergency plan. As such, the critical task should state, at a minimum, "The reactor failed to trip".

Recommendation: Replace critical task for item #5 to read as follows: "The reactor failed to trip (or words to this effect)".

If you have any questions or require additional information, please contact Mr. Barry A. Garber at (757) 365-2725.

Very truly yours,

Donald Jernigan Site Vice President

Commitments made by this letter: None

Serial No. 08-0218 Docket Nos. 50-280 50-281

cc: Mr. M. T. Widmann, Chief
Operations Branch
United States Nuclear Regulatory Commission Region II
Sam Nunn Atlanta Federal Center
61 Forsyth Street, SW, Suite 23 T85
Atlanta, Georgia 30303-8931

Mr. F. J. Ehrhardt Chief Examiner United States Nuclear Regulatory Commission Region II Sam Nunn Atlanta Federal Center 61 Forsyth Street, SW, Suite 23 T85 Atlanta, Georgia 30303-8931

Document Control Desk United States Nuclear Regulatory Commission Washington, D.C. 20555-0001

Senior Resident Inspector Surry Power Station