NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201			U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: RAM Services Incorporated Two Rivers, Wisconsin			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210		
REPORT NUMBER(S)		8-001	Lisle, Illinois 6053		
3. DOCKET NUMBER(030-33812	S) 	4. LICENSEE NUM 48-26638-01	BER(S)	5. DATE(S) OF INSP 4/.8/2008	PECTION
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
cited. This form is a			elow and/or attached, were in ect to posting in accordance		ents and are being
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title LICENSEE'S	Pri	inted Name	Sig	nature	Date
REPRESENTATIVE				1	
NRC INSPECTOR	Michael LaFra	nzo	mul M Lo	Trans	4/11/08
NRC FORM 591M PART 1 (10-20	003)			//	