NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INS	SPECTION REPORT	AND COMPLIANCE IN	NSPECTION	
LICENSEE/LOCATION INSPECTED: Center for Heart and Vascular Studies 1531 Amberley Forest Road Virginia Beach , VA 23453 REPORT Nos 2008001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPEC	CTION
03029553 LICENSEE:	45-24873-01		4/1-2/0	8
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of proceduces and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1				
Licensee's	Statement of Corre	ctive Actions for Item	4, above.	
I hereby state that, within 30 days, the actions donorective actions is made in accordance with the date when full compliance will be achieved). I un	e requirements of 10 CFR	2.201 (corrective steps alre-	ady taken, corrective step	s which will be taken,
Title Prir	nted Name	Si	gnature	Date
LICENSEE'S REPRESENTATIVE LONALD	(K. Hopu	V 681		1/2/88
NRC INSPECTOR Thomas K	. Thompson	Thomas &	Kimph	4/2/08
NRC FORM 591M PART 1 (Rev. by RI 07/06)		G:\Docs\Current\In	sp Record\45-24873-01.2	2008001.591MP1.wpd

SUNSI Review Completed By: /RA/

X Public

X Non-Sensitive