

**TREAT AS
SENSITIVE
INFORMATION**

Environmental Services

Rich Dailey, Sr. Director

Radiation Safety Officer

1300 SE 8th Street, MS 0605
Bentonville, AR 72716-0605
Phone 479.204.9914
Rich.Dailey@wal-mart.com
www.walmart.com

May 21, 2008

Director Charles Miller
Office of Federal and State Materials
and Environmental Management Programs
U.S. Nuclear Regulatory Commission
One White Flint North
11545 Rockville Pike
Rockville, MD 20852

Subject: Report of Damaged Tritium Exit Sign

Dear Director Miller:


Pursuant to 10 CFR § 31.5(a), Wal-Mart Stores, Inc. ("Wal-Mart") is a general licensee of the Nuclear Regulatory Commission ("NRC") because it possesses and uses byproduct material in the form of tritium exit signs ("TES") regulated by the NRC. Consistent with 10 CFR § 31.5(c)(5), Wal-Mart is providing the subject report regarding one damaged TES that it discovered at its store #1009, located in Republic, Missouri.

Attachment A provides a brief description of the events associated with the damaged TES and corrective actions taken. Information on the damaged TES is provided below:

<u>Serial #</u>	<u>Curies</u>	<u>Damage Date</u>	<u>Store Location</u>
268058	20.0	Prior to 09/2007	1150 U.S. Highway 60 East Republic, MO

Please contact me at (479) 204-9914, if you have any questions regarding this letter or the attached report.

Sincerely,



for Richard Dailey
Radiation Safety Officer
Wal-Mart Stores, Inc.

cc: Karen Roberts, Wal-Mart Stores, Inc.
Thomas Poindexter, Morgan Lewis & Bockius LLP

FSME10
FSME

Attachment A

A. Description of Events

On April 21, 2008, Wal-Mart representatives and its contractor Shaw Group, Inc. ("Shaw") visited Wal-Mart store #1009, in Republic, Missouri, to inventory tritium exit signs ("TES"). Wal-Mart has retained Shaw, an environmental services contractor with extensive experience with the management of radioactive material, for its company-wide program to inventory and manage TES. During the inventory at the Republic store, Shaw discovered one damaged TES with one tritium-containing tube in the "I" broken. The TES was installed in the non-public receiving area of the store.

B. Actions Taken

Interviews with the store managers and associates provided little information as to the cause or date of damage to the TES. One associate said the damage occurred more than 8 months ago, when he began working at the Republic store. Although the damage was not recent, the Wal-Mart Radiation Safety Officer ("RSO") directed a Certified Health Physicist ("CHP") from Dade Moeller & Associates ("Dade Moeller") to visit the Republic store to conduct radiological surveys, package the TES for disposal, and decontaminate the area to ALARA levels, as necessary. Dade Moeller is a contractor retained by Wal-Mart with the responsibility to assess the radiological impacts of damaged TES. The CHP is scheduled to visit the Republic store on May 28, 2008. Wal-Mart will provide the NRC with a report of the final as-left contamination levels within 30 days of the date of this report.

C. Long-term Corrective Actions

Wal-Mart has implemented and communicated protocols to its stores for the proper handling of TES to ensure public health and safety and the protection of its employees. It is also inventorying all of the TES at its sites across the country to re-establish the accuracy of its records and to track the current locations of the TES. The intent of this program is to ensure that all TES are accounted for and are handled properly. As a part of this program, Wal-Mart has employed Shaw to inventory TES, and a team of CHPs from Dade Moeller to properly handle TES and prepare and arrange for their return to a specific licensee.

D. Shipping Details

Wal-Mart anticipates shipping the damaged TES to a specific licensee authorized to receive the damaged TES, within 30 days of this report.