

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: STS Acquisition Co. Green Bay, WI; Milwaukee, WI; Grand Rapids, MI REPORT NUMBER(S) 2008-001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) 030-14020	4. LICENSEE NUMBER(S) 48-18672-01	5. DATE(S) OF INSPECTION 5/21-22/08


LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)



Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Michael M LaFranco		5/28/08

SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE STS Acquisition Company REPORT NUMBER(S) 2008-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-14020	4. LICENSE NUMBER(S) 48-18672-01	5. DATE(S) OF INSPECTION 5/21 and 22/08	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 3.1 – 3.7		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Mark Manske – RSO	4. TELEPHONE NUMBER 414-577-1329
----------------------------	------------------	--	-------------------------------------

<input checked="" type="checkbox"/>	Main Office Inspection	Next Inspection Date: 5/2013
<input checked="" type="checkbox"/>	Field Office Grand Rapids, Michigan	
<input type="checkbox"/>	Temporary Job Site Inspection	

PROGRAM SCOPE

The licensee was authorized to use and store licensed material at five permanent field stations and temporary job sites within NRC jurisdiction. At the time of the inspection, the licensee only had licensed material at the Grand Rapids and Marquette, Michigan field stations. The licensee had 15 gauges out of the Grand Rapids site and eight gauges out of the Marquette site. The licensee employs approximately 25 individuals throughout the company.

Performance Observations

The inspector interviewed the RSO and several gauge operators and found that the licensee staff had adequate knowledge to ensure safe use of the gauge. The inspector reviewed the licensee's leak test records, inventory, transportation documentation and dosimetry records; no abnormal issues were identified. No licensed operations were on-going within NRC jurisdiction at the time of the inspection. The licensee demonstrated the proper methods to transport and store the gauge when not in use.