

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: <i>Decorative Panels International, Inc. Alpena, Michigan</i>		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
REPORT NUMBER(S) <i>2008-001</i>			
3. DOCKET NUMBER(S) <i>030-04843</i>	4. LICENSEE NUMBER(S) <i>21-05856-01</i>	5. DATE(S) OF INSPECTION <i>6/5/08</i>	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)



Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	<i>Michael McLaughlin</i>	<i>Debra M. [Signature]</i>	<i>6/5/08</i>

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Decorative Panels International, Inc. REPORT NUMBER(S) 2008-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 03004843	4. LICENSE NUMBER(S) 21-05856-01	5. DATE(S) OF INSPECTION 6/5/2008	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 3.01-3.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Dan Fluker – RSO	4. TELEPHONE NUMBER 989-356-2151
----------------------------	------------------	---	-------------------------------------

<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: June 2013
<input type="checkbox"/> Field Office	
<input type="checkbox"/> Temporary Job Site Inspection	

PROGRAM SCOPE

The licensee is a manufacturer of 8'x4' wooden panels for wall decoration in the US. The licensee possesses six fixed gauges containing Cs-137 for measurement use. The licensee has not had any changes since the last inspection; however, the current RSO plans to retire in the next few years. All gauges are at a single address at the licensee's facility. The licensee is not authorized to relocate gauges throughout the plant.

Performance Observations

The inspector performed an inventory of each gauge possessed by the licensee; all gauges were accounted for and were operating properly during the inspection. The inspector interviewed the RSO and other workers at the plant and found that each individual interviewed had adequate knowledge to ensure the safe use of licensed material. The inspector reviewed the licensee's leak tests, inventories and shutter tests; no abnormal issues were identified.

During the last inspection, a violation of NRC requirements was identified regarding the unauthorized relocation of a gauge at the site. The inspector verified that procedures were in place to prevent recurrence and no such recurrence had taken place. The violation is considered closed.