



UNITED STATES  
 NUCLEAR REGULATORY COMMISSION  
 REGION II  
 101 MARIETTA ST., N.W., SUITE 3100  
 ATLANTA, GEORGIA 30303

TERA

DEC 31 1979

In Reply Refer To:

RII:JPO

50-438, 50-439

50-259, 50-260

50-296, 50-518

50-519, 50-520

50-521, 50-553

50-554, 50-327

50-328, 50-390

50-391, 50-566

50-567

Tennessee Valley Authority

Attn: H. G. Parris

Manager of Power

500A Chestnut Street Tower II

Chattanooga, Tennessee 37401

Gentlemen:

The enclosed IE Information Notice No. 79-36 provides information on a computer code defect which can result in incorrect stress values for piping elbows.

Sincerely,

James P. O'Reilly  
 Director

Enclosures:

1. IE Information Notice  
 No. 79-36
2. List of Recently Issued  
 Information Notices

1797-163

8001240 069

Tennessee Valley Authority

-2-

cc w/encl:

A. M. Qualls  
Plant Superintendent  
Post Office Box 2000  
Hollywood, Alabama 35752

W. R. Dahnke, Project Manager  
Post Office Box 2000  
Hollywood, Alabama 35752

J. F. Cox  
400 Commerce Street  
W10C131 C-K  
Knoxville, Tennessee 37902

D. L. Terrill  
Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

H. L. Abercrombie  
Plant Superintendent  
Post Office Box 2000  
Decatur, Alabama 35602

D. E. McCloud  
Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

R. T. Hathcote, Project Manager  
Post Office Box 2000  
Hartsville, Tennessee 37074

J. E. Wills, Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

W. P. Kelleghan, Project Manager  
Post Office Box 2000  
Surgoinville, Tennessee 37873

G. G. Stack, Project Manager  
Post Office Box 2000  
Daisy, Tennessee 37319

cc w/encl: (Continued on Page 3)

1797 164

DEC 31 1979

Tennessee Valley Authority

-3-

cc w/encl: (Continued from Page 2)

J. M. Ballentine  
Plant Superintendent  
Post Office Box 2000  
Daisy, Tennessee 37319

D. L. Lambert, Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

J. F. Groves, Plant Superintendent  
Post Office Box 2000  
Spring City, Tennessee 37381

Joseph E. Wilkins, Project Manager  
Post Office Box 2000  
Spring City, Tennessee 37381

M. M. Price, Project Manager  
Post Office Box 2000  
Iuka, Mississippi 38852

E. G. Beasley  
Tennessee Valley Authority  
309 Grant's Building  
Knoxville, Tennessee 37902

1797 165



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6870  
Accession No:  
7910250519

December 31, 1979

DUPLICATE

IE Information Notice No. 79-36

COMPUTER CODE DEFECT IN STRESS ANALYSIS OF PIPING ELBOW

Description of Circumstances:

The NRC was informed on December 17, 1979 that a computer code, NUPIPE, used in the stress analysis of piping systems contained a defect which could result in incorrect stress values at one end of piping elbows. This defect was identified from discussions with a user of NUPIPE and the NUPIPE code developers. The stress calculation error can occur when a flexible joint is modeled at the end of an elbow (ELBOW-ELASTOJT connection in NUPIPE terminology). This defect in the NUPIPE code is in the transformation of the loads in the ELASTOJT coordinate axis to the piping ELBOW coordinate axis. The incorrect coordinate axis transformation may incorrectly interchange the torsion and bending moment loads on the piping elbow. This can result in the incorrect assignment of the stress intensification factor for the individual moments. The correct stress may be higher or lower than calculated by NUPIPE, depending on the loading condition.

Four conditions must exist for the possibility of the calculation of an incorrect stress in the NUPIPE code:

1. an USAS B31.1.0 - 1967 Code analysis is being done, and
2. an ELBOW-ELASTOJT connection exists, and
3. an absolute sum of two load cases is being calculated, and
4. the ELBOW torsional moment axis does not align with the ELASTOJT local x-axis.

Possible users of the NUPIPE code include the code developer, Stone and Webster, EG&G (Idaho Falls), and those using the Cybernet system. The NRC is currently reviewing the extent of usage of the NUPIPE code and the generic implications for other facilities. There is a potential for a similar defect to occur in other piping analysis computer codes.

This Information Notice is provided as early notification of a possible significant matter. It is expected that recipients will review the information for possible applicability to their facilities. No specific action is requested in response to this Information Notice. If NRC evaluations so indicate, further licensee actions may be requested or required. If you have any questions regarding this matter, please contact the Director of the appropriate NRC Regional Office.

No written response to this IE Information Notice is required.

1797 166

IE Information Notice No. 79-36  
December 31, 1979

Enclosure

RECENTLY ISSUED  
IE INFORMATION NOTICES

Information Notice No.	Subject	Date Issued	Issued To
79-36	Computer Code Defect In Stress Analysis of Piping Elbow	12/31/79	All holders of power reactor OLs and CPs
79-35	Control of Maintenance and Essential Equipment	12/31/79	All holders of power reactor OLs and CPs.
79-34	Inadequate Design of Safety-Related Heat Exchangers	12/27/79	All holders of power reactor OLs and CPs
79-33	Improper Closure of Primary Containment Equipment Access Hatches	12/21/79	All holders of power reactor OLs and CPs
79-32	Separation of Electrical Cables for HPCI and ADS	12/21/79	All power reactor facilities holding OLs and CPs
79-31	Use of Incorrect Amplified Response Spectra (ARS)	12/13/79	All power reactor facilities holding OLs and CPs
79-30	Reporting of Defects and Noncompliances, 10 CFR Part 21	12/6/79	All power reactor facilities holding OLs and CPs and vendors inspected by LCVIP
79-29	Loss of NonSafety-Related Reactor Coolant System Instrumentation During Operation	11/16/79	All power reactor facilities holding OLs or CPs
79-28	Overloading of Structural Elements Due to Pipe Support Loads	11/16/79	All power reactor facilities with an OL or CP
79-27	Steam Generator Tube Ruptures At Two PWR Facilities	11/16/79	All power reactor facilities holding OLs and CPs
79-12A	Attempted Damage To New Fuel Assemblies	11/9/79	All Fuel Facilities, research reactors, and power reactors with an OL or CP
79-26	Breach of Containment Integrity	11/5/79	All power reactor facilities holding OLs and CPs
79-25	Reactor Trips At Turkey Point Units 3 And 4	10/1/79	All power facilities with an OL or a CP

1797 167