Docket Nos. (See attached page)

JAN 4 1973

Dr. Chester P. Siess Chairman, Advisory Committee on Reactor Safequards U. S. Atomic Energy Commission Washington, D. C. 20545

Dear Dr. Siess:

Sizteen copies of the following are transmitted for the information of the Committee:

Letter regarding postulated pipe failures outside of the containment structure, including the rupture of a main steam or feedwater line, sent to the licenses and applicants on the attached list.

Distribution: Docket file PWR-2 MService (2) Project Managers Sincerely,

Richard C. DeYoung, Assistant Director for Pressurized Water Reactors

Directorate of Licensing

Enclosures: As stated

PWR-2 PWR-2 OFFICE > mis Kknie1 MService:bn DATE - 1/3/23

Docket Nos.

50-348, 50-364	Alabama Power Company (Joseph M. Farley 1 & 2)
50-247, 50-296	Consolidated Edison Company (Indian Point 2 & 3)
50-250, 50-251	Florida Power & Light Company (Turkey Point 3 & 4)
50-315, 50-316	Indiana & Michigan Electric Company (Donald C. Cook 1 & 2)
50-382	Louisiana Power & Light Company (Waterford 3)
50-282, 50-306	Northern States Power Company (Prairie Island 1 & 2)
50-275, 50-323	Pacific Gas & Electric Company (Diablo Canyon 1 & 2)
50-327, 50-328	Tennessee Valley Authority (Sequoyah 1 & 2)
50-390, 50-391	Tennessee Valley Authority (Watts Bar 1 & 2)
50-266, 50-301	Wisconsin Electric Power Company (Point Beach 1 & 2)
50-305	Wisconsin Public Service Corporation (Kewaunee)

NOTE: Sixteen copies of enclosures are attached. Enclosures are identical except for Prairie Island letter.