## TENNESSEE MALLEY AUTHORITY

CHATTANOOSA, TENNESSEE 37401

400 Chestnut Street Tower II

///N 25 A 8 June 23, 1982

WBRD-50-390/82-26 WBRD-50-391/82-23

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Merietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - INCORRECT LUBE OIL USED IN DIESEL GENERATORS - WBRD-50-390/82-26, WBRD-50-391/82-23 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on February 25, 1982 in accordance with 10 CFR 50.55(e) as NCR W-88-P. Our first interim report was submitted on March 30, 1982. TVA is still in the process of investigating the subject deficiency. We are investigating the program deficiency that allowed the incorrect oil to be approved for use and its continued use during additions and oil changes. We expect to submit our next report on or about September 1, 1982.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

IE 27