

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

September 15, 1982

WBRD-50-390/82-17, -391/82-16
BLRD-50-438/82-12, -439/82-12
HTRD-50-518/82-07, -520/82-07
YCRD-50-566/82-06, -567/82-06

U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

WATTS BAR, BELLEFONTE, HARTSVILLE, AND YELLOW CREEK NUCLEAR PLANTS
REPORTABLE DEFICIENCY - REGIONAL QUALITY ENGINEERING BRANCH INSPECTION
OFFICE MANPOWER -WBRD-50-390/82-17, -391/82-16 - BLRD-50-438/82-12,
-439/82-12, -HTRD-50-518/82-07, -520/82-07, -YCRD-50-566/82-06, -567/82-06

The subject deficiency was initially reported to NRC-OIE, Region II, Inspector Don Quick on January 20, 1982 as NCR M80-11 Deficiency No. 3. Our first and second interim reports were submitted on March 1 and June 3, 1982 respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes our third interim report on the subject deficiency. TVA's Division of Engineering Design has conducted a study of all aspects of the procurement process. The preparation, review, handling content, and approvals of the process were included. The study is currently being evaluated by EN DES management. TVA anticipates transmitting the next report on or before March 18, 1983. If you have any questions, please call Jim Domer for BWRs at FTS 858-2725 or Ralph Shell for PWRs at FTS 858-2676.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


L. M. Mills, Manager
Nuclear Licensing

cc: Mr. R. C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8209220237 820915
PDR ADOCK 05000390
S PDR

OFFICIAL COPY

TE 27