

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 19, 1982

WBRD-50-390/81-33

WBRD-50-391/81-32

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPER CLASSIFICATION OF ERCW
SYSTEM PIPING AND COMPONENTS - WBRD-50-390/81-33, WBRD-50-391/81-32 -
EIGHTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on March 24, 1981 in accordance with 10 CFR 50.55(e) as NCR WBN NEB 8106, concerning the seismic qualification for chillers/coolers and deficient piping of the HVAC system. A similar deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on May 7, 1981 in accordance with 10 CFR 50.55(e) as NCR 3116R R1, concerning improper classification of ERCW system piping. Interim reports were submitted on April 24, June 8, July 14, September 2, and December 9, 1981 and February 17 and August 11, 1982. Our last submittal constituted a final report on NCR 3116R R1 (WBRD-50-390/81-50, WBRD-50-391/81-48). We expect to submit our next report on NCR WBN NEB 8106 on or about April 27, 1983.

TVA is continuing the evaluation of the secondary safety-related equipment which was described in our last report. We are also investigating other alternatives to resolve this deficiency.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

D S Kammer

for L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

82 OCT 21 9 53

USNRC REGION II
ATLANTA, GEORGIA

OFFICIAL COPY

8210260390 821019
PDR ADOCK 05000390
8 PDR

IC 27