## TENNESSEE VALLEY AUTHORITY STATISTICS SERVER SERVE

February 28, 1983 83 MAR 2 PI2: 52

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - NRC-OIE REGION II INSPECTION REPORT 50-390/82-35 AND 50-391/82-32 - SUPPLEMENTAL RESPONSE TO VIOLATIONS 50-390/82-35-01, 50-391/82-32-01

The subject Inspection Report dated November 2, 1982 cited TVA with two violations. Our response to the subject violations was submitted on January 17, 1983.

In our previous submittal, TVA committed to develop and issue a criteria, by February 20, 1983, which is to be used in determining when operational constraints and alignment checks will be required as a consequence of piping and/or hanger construction work being performed in the vicinity of applicable safety-related components.

As discussed with NRC-OIE Region II Inspector Linda Watson on February 16-17, 1983, TVA anticipated that the date of February 20, 1983 for the issuance of the above mentioned criteria would not be met. Inspector Watson was informed that the criteria was in the final review process and an extension to March 1, 1983 was granted for the completion of this corrective action.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

To the best of my knowledge I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Licensing

oc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555