

TENNESSEE VALLEY AUTHORITY
USNRC REGION II
ATLANTA, GEORGIA
CHATTANOOGA, TENNESSEE
400 Chestnut Street Tower II

November 5, 1981 A 8:46

SQRD-50-328/81-24
WBRD-50-390/81-28, -391/81-27
BLRD-50-438/81-25, -439/81-27
YCRD-50-566/81-07, -567/81-05
HTRD-50-518/81-11, -519, -520, -521/81-09
PBRD-50-553/81-12, -554/81-07

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

SEQUOYAH UNIT 2, WATTS BAR, BELLEFONTE, YELLOW CREEK, HARTSVILLE, AND
PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCIES - PROCUREMENT
CONTROL ACTIVITIES -SQRD-50-328/81-24 -WBRD-50-390/81-28, -391/81-27 -
BLRD-50-438/81-25, -439/81-27 - YCRD-50-566/81-07, -567/81-05 - HTRD-50-
518/81-11, -519, -520, -521/81-09 - PBRD-50-553/81-12, -554/81-07

The subject deficiencies were initially reported to NRC-OIE, Region II,
Inspector R. Crlenjak on March 16, 1981 as a result of audit M80-11. The
first and second interim reports were submitted on April 16 and August 3,
1981, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part
50, this letter constitutes the third interim report on the subject
deficiencies. TVA is still in the process of evaluating the
deficiencies. A more detailed report of this evaluation will be provided
to your office on or before January 29, 1982. If you have any questions,
please call Ralph Shell for PWR's at FTS 858-2676 or Jim Domer for BWR's
at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8111130703 811105
PDR ADOCK 05000328
S PDR

OFFICIAL COPY

IE 22