

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar

Docket No. 50-391  
License No. CPPR-92

The following violation was identified during an inspection conducted on January 3 - 6, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion V, as implemented by Watts Bar FSAR Section 17, paragraph 17.1A.5 requires that activities affecting quality be prescribed by documented procedures and drawings and be accomplished in accordance with these procedures and drawings.

Watts Bar QCP 4.23-4, QCP4.23-5 and QCP 4.23-8 provide the procedures and acceptance criteria for inspection of the safety-related pipe supports and restraints.

Contrary to the above, between January 3 - 6, 1984, activities affecting quality were not being accomplished in accordance with documented procedures and drawings in that a reinspection of six hangers revealed two hangers with deviations from the documented requirements.

This is a Severity Level V (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JAN 23 1984

840316037B 840305  
PDR ADOCK 05000390  
PDR