

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

15 FEB 8 A7:52
WBRD-50-390/84-36

February 6, 1985

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 1 - INADEQUATE SEPARATION OF REDUNDANT
CABLES NEAR FLOOR OPENINGS - WBRD-50-390/84-36 - SUPPLEMENTAL INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector Dave Verrelli on July 23, 1984 in accordance with 10 CFR 50.55(e) as NCR WBN MEB 8430. Our first interim report was submitted on August 21, 1984 and our final report for unit 1 and second interim report for unit 2 was submitted on September 19, 1984.

The corrective action identified in our final report for unit 1 contained an inadvertent error. Special Engineering Procedure (SEP) 84-09 will be incorporated into the Watts Bar Design Criteria by August 1, 1986, rather than August 1, 1985 as indicated in our report. Please revise your records accordingly.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham

J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8503130086 850206
PDR ADOCK 05000390
S PDR