

10 853
TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

12 APR 14 30
400 Chestnut Street Tower II

April 9, 1982

WBRD-50-390/82-10
WBRD-50-391/82-10

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFECTIVE TUBE STEEL MATERIAL -
WBRD-50-390/82-10, WBRD-50-391/82-10 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector D. Quick on December 24, 1981 in accordance with 10 CFR 50.55(e) as NCR 3821R. This was followed by our first interim report dated January 29, 1982. TVA is still investigating this deficiency. We expect to submit our next report by May 28, 1982. We consider 10 CFR Part 21 applicable to this deficiency.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

820 128 0358

S

OFFICIAL COPY

IE 27
1/0